

## 2015 SERVICE BULLETIN/RECALL INDEX

Updated : 07/30/2015

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
<b><u>NEW RELEASE</u></b>			
05-007-15	07/25/2015	2015 BU	Front Brake Squeak/Squeal Noise
08-007-15 REV. A	07/29/2015	2015 D2 2015 DJ 2015 DS 2015 DX 2015 KL 2015 LA 2015 LD 2015 LX 2015 WD 2015 WK 2015 ZD	RG3 RG4 RJ3 RJ4 Radio Enhancements
08-027-15 REV. B	07/23/2015	2015 UF	RA2 Radio Software Enhancements
08-073-15	07/22/2015	2015 B1	Flash: False Vehicle Security Alarm Activation During Surveillance Mode
08-074-15	07/22/2015	2014-2015 VF	RA2 Radio Software Enhancements
08-075-15	07/23/2015	2015 KL 2015 LX 2015 UF 2015 WK	RL4 RK4 RM4 Radio Enhancements
08-076-15	07/23/2015	2014-2015 KL	Flash: BCM Diagnostic And System Improvements
08-077-15	07/29/2015	2015 BU	RA4 RG4 RJ4 Radio Enhancement
09-007-15	07/31/2015	2012-2016	Engine Oil Consumption Guideline
18-006-15 REV. E	07/25/2015	2013-2015 PF 2015 UF	Flash: 2.4L Powertrain Diagnostic and System Improvements

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
18-009-15 REV. B	07/23/2015	2014-2015 PF	Flash: MIL Illumination. Includes Various Drivability Improvements
18-010-15 REV. B	07/30/2015	2014-2015 FF	Flash:1.4L Diagnostic And System Improvements
18-032-15 REV. B	07/31/2015	2015 BF	Flash: 1.4L Diagnostic And System Improvements
18-056-15	07/24/2015	2015 4C	Clicking Noise From Auxiliary Water Pump Relay
18-057-15	07/25/2015	2013 D2 2013 DJ	Flash: 6.7L Diagnostic and System Improvements
18-058-15	07/31/2015	2015 KL	Engine Stop Start Not Available Message
21-023-15 REV. A	07/25/2015	2015 LD 2015 LX	Flash: Transmission Shift And Drivability Enhancements
21-037-15 REV. A	07/24/2015	2015 DS 2015 DX	Transmission Heater Assembly Reinforcement Plate
23-029-15	07/21/2015	2015 KL	Water In Right Front Floor Footwell
24-002-15	07/24/2015	2012-2013 WD	Flash: Rear HVAC Blower Controller Can Not Change Blower Speed
24-003-15	07/31/2015	2015 BU	Air Conditioning Inoperative
RC-CR38-15	07/24/2015	2015 WD 2015 WK	SAFETY RECALL R38 - REAR SUSPENSION LOWER CONTROL ARMS
RC-IR03-15	07/27/2015	2009-2010 JC 2008-2010 RT	Safety Recall R03 - Wireless Ignition Node Module
RC-IR38-15	07/24/2015	2015 WD 2015 WK	Safety Recall R38 - Rear Suspension Lower Control Arms
RC-R09-15	07/31/2015	2012-2013 WD	Safety Recall R09 - Fuel Pump Relay

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
		2011-2013 WK	
RC-R32-15	07/29/2015	2011-2015 JC	Safety Recall R32 - Engine Beauty Cover
RC-R38-15	07/24/2015	2015 WD 2015 WK	Safety Recall R38 - Rear Suspension Lower Control Arms
RC-R40-15	07/30/2015	2013-2015 D2 2013-2015 DD 2013-2015 DJ 2013-2015 DP 2013-2015 DS 2014-2015 KL 2015 LA 2015 LD 2015 LX 2015 UF 2014-2015 WD 2014-2015 WK 2013-2015 ZD	Safety Recall R40 - Radio Security Vulnerability

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
---------------	-------------------	---------------	----------------

### INDEX BY GROUP

#### GROUP 02 - FRONT SUSPENSION

02-001-15	01/10/2015	2011-2015	Shock Strut Weeping Condition Identification
02-002-15	01/27/2015	2014-2015	Steering Wheel Not Centered
02-003-15	01/27/2015	2014-2015	Vehicle Pulls Or Leads Right Or Left
02-004-15	02/27/2015	2014 KL 2013-2014 PF	Cold Temperature Squeak/Creak Noise While Turning The Steering Wheel
02-005-15 REV. B	04/30/2015	2015 4C	Front End Popping Noise While Driving Over Bumps

#### GROUP 03 - DIFFERENTIAL & DRIVELINE

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
03-001-15 REV. A	07/18/2015	2015 LA 2015 LD 2015 LX	Rear Half Shaft Vibration
03-002-15	06/06/2015	2014-2015 KL	Drone Noise At Steady State Engine RPM
<b><u>GROUP 05 - BRAKES</u></b>			
05-001-15	02/17/2015	2015 UF	Rear Brake Squeal Noise In Reverse
05-002-15	04/24/2015	2011-2015 WD 2011-2015 WK	Front Brake Squeak/Squeal Noise
05-003-15	05/27/2015	2015 VM	Rear Brake Noise
05-004-15	06/10/2015	2015 LD	Incorrectly Installed Front Wheel Speed Sensor Wire
05-005-15	06/20/2015	2014-2015 VF	Front Brake Squeak/Squeal Noise
05-006-15	07/11/2015	2012-2015 WK	Front Brake Squeak/Squeal Noise
05-007-15	07/25/2015	2015 BU	Front Brake Squeak/Squeal Noise
<b><u>GROUP 07 - COOLING</u></b>			
07-001-15	01/07/2015	2015 MK	Coolant Bottle Recovery Hose Improperly Attached
07-002-15 REV. A	03/31/2015	2013-2014 DS 2011-2014 JC 2011-2014 JS 2014-2015 KL 2011-2014 LC 2011-2014 LD 2011-2014 LX 2011-2014 RT 2011-2014 WD 2011-2014 WK	Idler Pulley Noise During Cold Start
07-003-15	01/23/2015	2011-2013 WK	Service Bulletin/RRT 07-003-14/14-057 Superseded By

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
			Customer Satisfaction Notification (CSN) P49
07-004-15	03/18/2015	2014-2015 DS 2015 DX	Malfunction Indicator Lamp (MIL) Illuminated DTC P1D73 Active Grill Shutter (AGS) Performance
07-004-15 REV. A	05/19/2015	2014-2015 DS 2015 DX	Malfunction Indicator Lamp (MIL) Illuminated DTC P1D73 Active Grill Shutter (AGS) Performance
07-005-15 REV. A	04/11/2015	2015 LA 2015 LD	Intermittent Coolant Weepage From Upper Radiator Hose
07-006-15	05/08/2015	2014 VF	Intermittent Coolant Loss
<b><u>GROUP 08 - ELECTRICAL</u></b>			
08-001-15	01/08/2015	2009-2010 JC 2008-2009 RT	L25 Interim Repair Procedure Brazil ONLY
08-002-15	01/08/2015	2005-2007 WK 2006-2007 XK	P41 Interim Repair Procedure Brazil ONLY
08-003-15	01/08/2015	2008 LX 2008 XK	P57 Interim Repair Procedure Brazil ONLY
08-004-15 REV. B	05/06/2015	2013-2015 FF	FLASH: Battery Electric Vehicle, Multiple System Enhancements
08-005-15	01/15/2015	2015 MK	Flash: Instrument Panel Cluster Does Not Show The Letter L
08-006-15	01/22/2015	2014 D2 2014 DD 2014 DJ 2014 DP 2014 DS 2014 DX	Flash: Incorrect Language Displayed In The Cluster
08-007-15 REV. A	07/29/2015	2015 D2 2015 DJ 2015 DS	RG3 RG4 RJ3 RJ4 Radio Enhancements

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
		2015 DX 2015 KL 2015 LA 2015 LD 2015 LX 2015 WD 2015 WK 2015 ZD	
08-008-15	01/23/2015	2011-2013 WK	Flash: DTC P0405 / P0406 - MIL Light On
08-010-15	01/23/2015	2012-2013 JC 2012-2013 LX	Flash: DTC B1A8A-00 - No Start Condition With a Low Battery
08-011-15	01/27/2015	2014 KL	B2128-17 - Sensor Supply Voltage - Circuit Voltage Above Threshold And/Or U045A-86 - Implausible Data Received From Parking Assist Module - Signal Invalid
08-012-15	02/10/2015	2014-2015 BF	Intermittent Battery Drain
08-013-15	02/13/2015	2014 KL	Flash: BCM Diagnostic And System Improvements
08-014-15	02/18/2015	2015 JK	RES RBZ RHB RHR Poor Audio Quality
08-015-15	02/25/2015	2013-2014 WK	Flash: Gear Shift Indicator System Enhancements
08-016-15 REV. A	06/23/2015	2013-2014 D2 2013-2014 DD 2013-2014 DJ 2013-2014 DP 2013-2014 DS 2014-2015 KL 2014-2015 WD 2014-2015 WK	Poor Radio Reception
08-017-15	02/27/2015	2015 JC 2014 LD 2014 LX 2015 PF	No Travel Link Data Displayed And Other System Enhancements

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
08-018-15	03/04/2015	2014-2015 JC 2014-2015 JF	Flash: Intrusion Transceiver Module Enhancements
08-019-15	03/04/2015	2011-2013 JK	Loss Of Power Heated Mirror Function - Recall P61
08-020-15	03/06/2015	2013 LD 2013 LX 2013-2014 RT	Flash: Blind Spot Monitor System Improvements
08-021-15 REV. A	03/21/2015	2015 4C	Flash: MIL Illumination And Transmission Over Temperature Message
08-022-15	03/11/2015	2014 JK 2014 RT	Service Tire Pressure System Message
08-023-15 REV. A	05/27/2015	2015 BU 2016 FB	Stored Diagnostic Trouble Codes (DTCs) Found During New Vehicle Preparation
08-024-15	03/11/2015	2014-2015 JC 2014-2015 LD 2014-2015 WD 2014-2015 WK	Flash: Service Tire Pressure System Message
08-025-15	03/12/2015	2015 MK	Flash: Auto Lock Feature Inoperative
08-026-15 REV. A	04/03/2015	2015 BU	Incorrect Language Displayed On The Cluster And Radio
08-027-15 REV. B	07/23/2015	2015 UF	RA2 Radio Software Enhancements
08-028-15 REV. A	07/09/2015	2015 D2 2015 DD 2015 DJ 2015 DP 2015 DS 2015 DX 2015 KL 2015 LD 2015 WD	RA2 Radio Software Enhancements

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
		2015 WK	
08-029-15 REV. A	07/09/2015	2015 D2 2015 DJ 2015 DP 2015 DS 2015 KL 2015 LD 2015 WD 2015 WK	RG2 Or RJ2 Radio Software Enhancements
08-030-15	03/27/2015	2014-2015 D2 2014-2015 DD 2014-2015 DJ 2014-2015 DP 2014-2015 DS	Auto Headlamp Enhancements
08-031-15 REV. A	07/16/2015	2015 D2 2015 DD 2015 DJ 2015 DP 2015 DS 2015 DX 2015 KL 2015 LA 2015 LD 2015 LX 2015 WD 2015 WK 2015 ZD	RA3 RA4 Radio Enhancements
08-032-15	03/31/2015	2013-2015 JC 2013-2014 LD 2013-2014 LX	RE9 Radio Software Enhancements
08-033-15	03/31/2015	2013-2015 JC 2013-2014 LD 2013-2014 LX	Flash: RE2 RE3 RE4 RE6 RE7 RB4 RB5 RB6 RB4 Radio Enhancements
08-034-15	04/07/2015	2011-2014 RT	Wire Harness Hanging Down From Rear Bumper Fascia

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
08-035-15 REV. A	07/16/2015	2015 UF	RA3 RA4 Radio Enhancements
08-036-15	04/16/2015	2014 VF	Front Door Speaker, Audio Distortion or Inoperative
08-037-15	04/17/2015	2013-2014 LC	Flash: Audio Enhancement, Reduce Audio Distortion
08-038-15	04/18/2015	2012 D2 2012 DD 2012 DJ 2012 DP 2012 DS 2012 DX 2012-2014 JK 2012-2014 JS 2012 KK 2012-2014 LC 2012-2014 MK 2012 PM 2012-2014 RT 2012-2013 WD 2012-2013 WK	RBZ Or RHB Radio Software Enhancements
08-039-15	04/18/2015	2013-2014 PF	Tire Pressure Monitoring System May Display Wrong Tire Location
08-040-15	04/24/2015	2015 LX	Passive Entry And/Or Trunk Latch Not Operating - Install Shorter License Plate Screws
08-041-15	04/29/2015	2013-2015 WD 2013-2015 WK	Front Heated Seats Improvements
08-042-15	04/28/2015	2015 DJ	Power Wagon Splash Screen Missing In The Electronic Vehicle Information Center (EVIC)
08-043-15	04/29/2015	2015 D2 2015 DJ	Mirror Fold/Unfold Switch Inoperative
08-044-15	04/30/2015	2015 4C	Tire Pressure Monitoring System (TPMS) Lamp Illuminated With Tires Inflated To Correct Pressure

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
08-045-15	04/30/2015	2015 WK	Media Hub Inoperative
08-046-15	05/02/2015	2015 LD	Passive Entry Door Unlock Setting Missing
08-047-15 REV. B	06/05/2015	2015 D2 2015 DD 2015 DJ 2015 DP 2015 DS 2015 DX 2015 LA 2015 LD 2015 LX	Low Beam Headlamps Dim Or Appear Yellow
08-048-15	05/05/2015	2015 ZD	Flash: Unable To Adjust Radio Volume And Or No Audio
08-049-15	05/05/2015	2015 FF	Inoperative Blue And Me Steering Wheel Button
08-050-15	05/06/2015	2015 LD 2015 LX	Flash: Poor Audio Sound Quality
08-051-15	05/08/2015	2015 JC	Passive Entry For Liftgate Inoperative
08-052-15	05/08/2015	2015 BU	Compass Direction Displayed Is 90 Degrees Off
08-053-15 REV. A	07/08/2015	2015 B1	Cluster Backlighting Dimming Incorrectly
08-054-15	05/15/2015	2015 UF	Proxi Issue After Mopar Accessory Remote Start Has Been Installed
08-055-15	05/16/2015	2011-2012 JC 2011-2012 LD 2011-2012 LX	RE2 RE3 RE6 RB4 RB5 RB6 Radio Enhancements
08-056-15	05/28/2015	2014-2015 KL	Improper Hood Switch Operation
08-057-15	05/29/2015	2013-2014 FF	Flash: Cruise Misspelled In The Instrument Panel Cluster

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
08-058-15	06/04/2015	2015 BU	Vehicle Will Not Start
08-059-15 REV. A	06/09/2015	2016 FB	Travel Link Button Not Displayed On The Radio Screen
08-060-15	06/10/2015	2015 BU	Flash: Doors May Not Unlock Using Remote Keyless Entry (RKE)
08-061-15	06/10/2015	2014 KL	Flash: Incorrect Cruise Control Set Speed Is Displayed
08-062-15	06/18/2015	2015 BU	RA2 Radio Software Enhancements
08-063-15	06/18/2015	2015 BU	Flash: Battery Drained After Sitting Overnight
08-064-15	06/20/2015	2015 VF	Roof Clearance Lamp Has Moisture Inside
08-065-15	06/20/2015	2015 UF	Front Seat Bottom Cushion Hard Or Lumpy Spot
08-066-15	06/26/2015	2015 BU	Flash: Improvements To Messages Displayed In The Cluster
08-067-15	06/30/2015	2014 KL 2014 WK	RM4 Radio Enhancements (Japan Only)
08-068-15	07/02/2015	2015 JK	Flash: Poor Audio Sound Quality
08-069-15	07/15/2015	2015 LX	Fuse Location Incorrectly Labeled
08-070-15	07/15/2015	2015 DS	Fuel Economy Information Is Missing
08-071-15	07/16/2015	2015 BU	Flash: BCM Update To Correct Various Symptoms
08-072-15	07/16/2015	2013-2014 D2 2013-2014 DD 2013-2014 DJ 2013-2014 DP 2013-2014 DS 2013-2014 DX 2014 KL 2014 WD	RA3 RA4 Radio Enhancements

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
		2014 WK 2013-2014 ZD	
08-073-15	07/22/2015	2015 B1	Flash: False Vehicle Security Alarm Activation During Surveillance Mode
08-074-15	07/22/2015	2014-2015 VF	RA2 Radio Software Enhancements
08-075-15	07/23/2015	2015 KL 2015 LX 2015 UF 2015 WK	RL4 RK4 RM4 Radio Enhancements
08-076-15	07/23/2015	2014-2015 KL	Flash: BCM Diagnostic And System Improvements
08-077-15	07/29/2015	2015 BU	RA4 RG4 RJ4 Radio Enhancement
<b><u>GROUP 09 - ENGINE</u></b>			
09-001-15	04/17/2015	2015 KL	Engine Crankshaft Built With Incorrect Tolerances
09-002-15 REV. A	04/29/2015	2014 D2 2014 DD 2014 DJ 2014 DP	Knocking Noise From Engine After Sitting Overnight
09-003-15	04/28/2015	2015 UF	Incorrect Bolt Length Used For Fastening Transmission To Engine
09-004-15	06/27/2015	2015 WK	Incorrect Engine Mount Isolator Installed On 3.0L Diesel Engine
09-005-15	07/03/2015	2015 LA	Right Side Engine Cover Missing With Shaker Package
09-006-15	07/18/2015	2014 DS 2014 WK	Intermittent Engine Shudder While Driving
09-007-15	07/31/2015	2012-2016	Engine Oil Consumption Guideline

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
<b><u>GROUP 10 - RESTRAINTS</u></b>			
10-001-15	05/16/2015	2015 KL 2015 UF	Intermittent Seat Belt Chime And Seat Belt Indicator Lamp On
<b><u>GROUP 11 - EXHAUST SYSTEM</u></b>			
11-001-15	01/28/2015	2014-2015 KL	Sputter Type Noise Emitted From Exhaust
11-002-15	06/10/2015	2015 D2 2015 DJ	Poor Weld On Muffler
<b><u>GROUP 13 - FRAMES &amp; BUMPERS</u></b>			
13-001-15 REV. A	04/24/2015	2015 JC 2015 JF	Right Front Side Rail Inner Panel Stamping Deformity
13-002-15	04/29/2015	2015 VF	Trailer Tow Package Not Installed On Vehicle
<b><u>GROUP 14 - FUEL SYSTEM</u></b>			
14-001-15	02/17/2015	2014-2015 KL	Diesel Fuel Filter Weepage in Extreme Cold Conditions
<b><u>GROUP 17 - REAR SUSPENSION</u></b>			
17-001-15	03/21/2015	2015 WD 2015 WK	Incorrect Bolts Used On Rear Shock Absorber Upper Mount
<b><u>GROUP 18 - VEHICLE PERFORMANCE</u></b>			
18-002-15	01/07/2015	2015 D2 2015 DD 2015 DJ	Flash: Diagnostic And System Enhancements
18-003-15	01/13/2015	2014 JS	Flash: PCM System Improvements For Hard Controlled Stops
18-004-15	01/13/2015	2013 DS	Flash: PCM System Improvements For Hard Controlled

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
			Stops
18-005-15 REV. C	04/23/2015	2014-2015 KL	Flash: 2.4L Powertrain Diagnostic And System Improvements
18-006-15 REV. E	07/25/2015	2013-2015 PF 2015 UF	Flash: 2.4L Powertrain Diagnostic and System Improvements
18-007-15 REV. B	06/02/2015	2015 KL	Flash: Diagnostic And System Improvements
18-008-15	01/21/2015	2014 LD	Flash: 3.6L Pursuit Powertrain Diagnostic And System Improvements
18-009-15 REV. B	07/23/2015	2014-2015 PF	Flash: MIL Illumination. Includes Various Drivability Improvements
18-010-15 REV. B	07/30/2015	2014-2015 FF	Flash:1.4L Diagnostic And System Improvements
18-011-15	01/28/2015	2015 LA	Flash: U0140 Lost Communication With Body Control Module
18-011-15 REV. A	03/11/2015	2015 LA 2015 LD 2015 LX	Flash: 3.6 Diagnostic And System Improvements
18-012-15	02/06/2015	2015 DD 2015 DP	Flash: 6.7L Diagnostic And System Improvements
18-013-15	02/07/2015	2015 D2 2015 DD 2015 DJ	Flash: U0140 Lost Communication With Body Control Module (BCM)
18-014-15	02/21/2015	2015 JC	Flash: 3.6L Or 2.4L Diagnostic and System Improvements
18-015-15	02/28/2015	2014-2015 DS	Malfunction Indicator Lamp (MIL) Illumination And/Or Intermittent No Crank No Start

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
18-016-15 REV. A	04/03/2015	2015 LA	Flash: 6.2L Powertrain Diagnostic And System Enhancements
18-017-15	03/03/2015	2015 RT	Flash: 3.6L Diagnostic And System Improvements
18-017-15 REV. A	06/15/2015	2015 RT	Flash: 3.6L Diagnostic And System Improvements
18-018-15	03/04/2015	2014 VF	Flash: 3.0L Diagnostic And System Improvements
18-018-15 REV. A	05/29/2015	2014 VF	Flash: 3.0L Diagnostic And System Improvements
18-019-15	03/04/2015	2015 DS	Flash: 3.0L Powertrain Diagnostic And System Enhancements
18-019-15 REV. A	06/02/2015	2015 DS	Flash: 3.0L Powertrain Diagnostic And System Enhancements
18-020-15	03/10/2015	2012-2013 PF	Flash: MIL Illumination P1D73, P1CEA And/Or P0456 Includes Various Driveability Enhancements
18-021-15 REV. B	05/28/2015	2014 DS	Flash: 3.0L Powertrain Diagnostic And System Enhancements
18-021-15 REV. C	06/10/2015	2014 DS	Flash: 3.0L Powertrain Diagnostic And System Enhancements
18-022-15 REV. A	07/03/2015	2015 WK	Flash: 3.0L Powertrain Diagnostic And System Enhancements
18-023-15 REV. B	05/28/2015	2014 WK	Flash: 3.0 L MIL Illumination Diagnostic and System Improvements
18-024-15	03/13/2015	2015 JK	Flash: U0140 Lost Communication With Body Control Module
18-025-15	03/31/2015	2011-2014 MK	Flash: Powertrain Diagnostic And System Enhancements

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
18-027-15 REV. A	04/18/2015	2012-2013 FF	Flash:1.4L Diagnostic And System Improvements
18-028-15	04/08/2015	2015 JC	Flash: Powertrain Diagnostic And System Enhancements
18-029-15	04/08/2015	2015 JK	Flash: Engine Oil Temp Too Low After Extended Idle
18-030-15 REV. A	07/08/2015	2016 FB	Flash: Powertrain Diagnostic And System Enhancements
18-031-15	04/15/2015	2014 JC	Flash: 2.4L, 3.6L Powertrain System Improvements/Enhancements
18-032-15 REV. B	07/31/2015	2015 BF	Flash: 1.4L Diagnostic And System Improvements
18-033-15	04/16/2015	2014 BF	Flash: 1.4L Powertrain Diagnostic And System Improvements
18-035-15 REV. A	06/23/2015	2015 LA 2015 LD 2015 LX	Flash: 6.2L / 6.4L Diagnostic And System Improvements
18-036-15	04/27/2015	2015 WK	Flash: 6.4L Powertrain Diagnostic And System Enhancements
18-037-15	04/30/2015	2015 DS	Flash: 5.7L P26AB Engine Coolant Bypass Valve Stuck
18-038-15 REV. A	05/20/2015	2015 VF	Flash: 3.0L Powertrain Diagnostic And System Enhancements
18-039-15	05/05/2015	2014 LC 2014 LD 2014 LX	Flash: 6.4L Powertrain Diagnostic And System Enhancements
18-040-15	05/05/2015	2014 MK	Flash: Diagnostic And System Improvements
18-041-15	05/06/2015	2015 D2 2015 DJ	Flash: 6.7L Diagnostic And System Improvements

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
18-043-15 REV. A	07/10/2015	2015 BU	Flash: 2.4L Powertrain Diagnostic And System Enhancements
18-044-15	05/21/2015	2014 WK	Flash: Power Control Module Software Enhancements
18-045-15	05/20/2015	2014 D2 2014 DJ	Flash: 6.7L Diagnostic And System Improvements
18-046-15	05/27/2015	2015 LA 2015 LD 2015 LX	Flash: 5.7L Diagnostic And System Improvements
18-047-15	05/28/2015	2015 WK	Flash: 3.0L Powertrain Diagnostic And System Enhancements
18-048-15 REV. A	07/17/2015	2015 VM	Flash: 2.4L Powertrain Diagnostic And System Enhancements
18-049-15	06/09/2015	2015 LX	Flash: 6.4L Diagnostic And System Improvements
18-050-15 REV. A	07/02/2015	2011-2014 LC	Flash: 3.6L Powertrain Diagnostic And System Enhancements
18-051-15	06/19/2015	2015 VF	Flash: 3.6L Powertrain Diagnostic And System Enhancements
18-052-15	07/02/2015	2013-2014 LC 2014 LD 2014 LX	Flash: 5.7L Powertrain Diagnostic And System Enhancements
18-053-15	06/25/2015	2012-2015 JK	Malfunction Indicator Lamp (MIL) Illumination P0344 - Camshaft Position Sensor Intermittent
18-054-15	06/27/2015	2010-2015 RT	Mil Illumination: P2453,P2454,P2455 or P2463 Active or Stored
18-056-15	07/24/2015	2015 4C	Clicking Noise From Auxiliary Water Pump Relay
18-057-15	07/25/2015	2013 D2	Flash: 6.7L Diagnostic and System Improvements

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
		2013 DJ	
18-058-15	07/31/2015	2015 KL	Engine Stop Start Not Available Message
<b><u>GROUP 19 - STEERING</u></b>			
19-001-15 REV. A	02/26/2015	2015 LA	Loss Of Power Steering Assist
19-002-15	04/08/2015	2012-2015 FF	Clunking Noise From The Steering Column While Turning The Steering Wheel
19-003-15	04/10/2015	2015 LA	Intermittent Power Steering Noise And/Or Slight Loss Of Assist
<b><u>GROUP 21 - TRANSMISSION AND TRANSFER CASE</u></b>			
21-001-15 REV. A	02/12/2015	2014-2015 KL 2015 UF	Service Bulletin/RRT 21-001-15/15-003 Superseded By Customer Satisfaction Notification (CSN) R01
21-002-15	01/21/2015	2015 KL	Start Stop Feature Inoperative After Transmission Replacement
21-003-15	01/24/2015	2014 W2 2014 W3 2014 WD 2014 WK	Flash: 8HP70 Transmission Shift Enhancements
21-004-15	01/24/2015	2014 DS 2014 LD 2014 LX 2014 W6 2014 WD 2014 WK	Flash: 845RE Transmission Shift Enhancements
21-005-15 REV. A	05/07/2015	2014 WK	Flash: Transmission Shift And Drivability Enhancements
21-006-15 REV. A	04/03/2015	2015 LA	Flash: 845RE Transmission Shift Enhancements

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
21-007-15	01/30/2015	2014-2015 KL	9 Speed Transmission Shift Enhancements - Adaptation Learn Procedure
21-008-15 REV. A	02/07/2015	2014-2015 KL 2015 UF	Transmission Shift Quality C-Clutch Snap Ring
21-009-15	02/20/2015	2015 LA	Flash: Transmission Shift And Drivability Enhancements
21-009-15 REV. A	03/31/2015	2015 LA	Flash: Transmission Shift And Drivability Enhancements
21-010-15	02/06/2015	2014-2015 KL 2015 UF	9 Speed Tutorial Awareness
21-011-15	02/28/2015	2014-2015 MK	Transmission Fluid Overfill After Repair
21-012-15	02/28/2015	2014 WK	Flash: Transmission Shift Enhancements
21-013-15	03/03/2015	2013-2014 D2 2013-2014 DD 2013-2014 DP	Flash: AS69RC/AS66RC Transmission Shift And Diagnostic Enhancements
21-014-15	03/04/2015	2015 DS	Flash: 8HP70 Transmission Shift Quality And Drivability Enhancements
21-015-15 REV. A	04/03/2015	2014-2015 KL 2015 UF	Flash: C1499-92-RDM Motor Position C1496-92-PTU Motor Position
21-016-15 REV. A	05/22/2015	2015 KL	Flash: Transmission Shift And Drivability Enhancements
21-017-15	03/21/2015	2015 LD 2015 LX	Flash: W5A580 Transmission Shift Enhancements
21-018-15	03/25/2015	2015 WK	Flash: 8HP70 SRT Transmission Shift Enhancements
21-019-15	03/31/2015	2015 LA	Flash: Transmission Shift And Drivability Enhancements
21-020-15	03/31/2015	2015 LD	Flash: Transmission Shift And Drivability Enhancements

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
		2015 LX	
21-021-15 REV. B	06/20/2015	2015 KL 2015 UF	Flash: Transmission Diagnostic And Shift Enhancements
21-022-15	04/10/2015	2015 LD 2015 LX	Flash: Transmission Shift And Drivability Enhancements
21-023-15 REV. A	07/25/2015	2015 LD 2015 LX	Flash: Transmission Shift And Drivability Enhancements
21-024-15 REV. A	05/30/2015	2016 FB	Flash: Transmission Shift And Drivability Enhancements
21-025-15	04/18/2015	2015 DS	Flash: 854RE Transmission Shift Enhancements
21-026-15	04/21/2015	2014-2015 J3 2014-2015 J8 2014-2015 JK	Flash: Transmission Shift And Drivability Enhancements
21-027-15	04/21/2015	2015 WD 2015 WK	Flash: Transmission Shift Enhancements
21-028-15	04/25/2015	2015 DS 2015 WD 2015 WK	Flash: 8HP70 Transmission Shift Enhancements
21-029-15	05/05/2015	2014 LC	Flash: Transmission Shift And Drivability Enhancements
21-030-15	05/09/2015	2015 BU	Flash: Transmission Shift And Drivability Enhancements
21-031-15	05/09/2015	2015 BF	Flash: Transmission Shift And Drivability Enhancements
21-032-15 REV. A	07/15/2015	2015 BU	Flash: Transmission Shift And Drivability Enhancements
21-033-15	05/20/2015	2014 KL	Flash: Transmission Shift And Drivability Enhancements
21-034-15	05/23/2015	2015 LX	Electronic Shifter Operation

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
21-035-15	05/27/2015	2013 JK 2013 LC 2013 WD 2013 WK	Flash: Transmission Shift Enhancements
21-036-15	05/29/2015	2015 FF	Flash: Transmission Shift And Drivability Enhancements
21-037-15 REV. A	07/24/2015	2015 DS 2015 DX	Transmission Heater Assembly Reinforcement Plate
21-038-15	06/04/2015	2015 BU	Flash: Drivetrain Control Module C2020-01 ECU Internal Fault setting in the DTCM
21-039-15	06/04/2015	2015 VM	Flash: Transmission Shift And Drivability Enhancements
21-040-15	06/05/2015	2015 BU	Flash: Transmission Shift And Drivability Enhancements
21-041-15	06/11/2015	2015 LX	Flash: Vehicle Will Not Shift Out Of Park
21-042-15	06/13/2015	2014 MK	Flash: Transmission Shift And Drivability Enhancements
21-043-15	06/19/2015	2014 KL	Flash: Transmission Shift and Diagnostic Enhancements
21-044-15	06/20/2015	2016 FB	Flash: Transmission Shift And Drivability Enhancements
21-045-15	07/03/2015	2015 WK	Flash: 8HP70 Transmission Shift Enhancements
21-046-15	07/16/2015	2015 RT	Low Transmission Fluid Level
21-047-15	07/18/2015	2016 FB	Flash: Transmission Shift And Drivability Enhancements

### GROUP 22 - TIRES AND WHEELS

22-001-15	01/30/2015	2015 LA	Incorrect Tire Pressure Sensor
22-002-15 REV. A	03/28/2015	2014-2015 D2 2014-2015 DD 2014-2015 DJ	Service Tire Pressure System Message

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
<b><u>GROUP 23 - BODY</u></b>			
23-001-15	01/09/2015	2015 DS	Lower Center Instrument Panel Bracket Fasteners Loose
23-002-15	01/17/2015	2015 MK 2015 PF	Key Code Missing
23-003-15	01/28/2015	2015 DS	Steering Column Buzz Squeak Rattle Noise And/Or Minor Movement
23-004-15	02/07/2015	2015 JK	Side Steps Are Missing
23-005-15	02/06/2015	2015 LD	Decklid Contacts The Body Side Aperture Above The Stop Lamp
23-006-15	02/13/2015	2014-2015 VF	Squeak Noise From Spare Tire Winch
23-007-15	02/21/2015	2015 W2 2015 W3 2015 W6 2015 W7 2015 WD 2015 WK	Rear Liftgate Will Not Open Intermittently
23-008-15	02/24/2015	2013-2015 RT	Rattle Noise From The Right Or Left Rear Sliding Door While Driving Over Bumps
23-009-15	03/04/2015	2014-2015 PF	Front Window Popping/Clicking Noise While Powered Up Or Down
23-010-15	03/18/2015	2015 LA	Removal Of Challenger SRT Hellcat Front Air Dam Shipping Covers
23-011-15	03/21/2015	2012-2014 JK	Tailgate Retaining Strap Over Extends And Breaks
23-012-15	03/31/2015	2014-2015 WD 2014-2015 WK	Cargo Compartment Load Floor Panel Latch Handle Broken
23-013-15	04/16/2015	2015 RT	Power Rear Liftgate Intermittently Will Not Open

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
23-014-15	04/23/2015	1990-2000 2001 BE 2001 BR	Child Seat Tether Anchor Installation
23-015-15	04/30/2015	2015 JK	Water Leak - Split Header Seal At End Mold
23-016-15	05/02/2015	2014-2015 KL	Front Passenger Fold Flat Seat Back Inoperative
23-017-15	05/16/2015	2015 UF	Key Codes Recorded Incorrectly
23-018-15	05/22/2015	2011-2015 LD 2011-2015 LX	Rattle Or Buzzing Noise In Rear Shelf Area With Radio On Or While Driving On Bumpy Roads
23-019-15	05/22/2015	2015 JK	Discolored Door Hinge Nuts
23-020-15 REV. A	07/08/2015	2015 B1	Replace Missing Manual Release Cover For The Electric Fuel Door
23-021-15	05/28/2015	2014-2015 KL	Squeak Noise Coming From The Rear Seat
23-022-15	06/04/2015	2015 WD 2015 WK	Door Glass Run Seal Weatherstrip Separated At Corner
23-023-15	06/05/2015	2015 UF	Wind Noise Dual Pane Sunroof
23-024-15	06/06/2015	2015 UF	Mirror Housing Surface Finish Does Not Match Mirror Flag Surface Finish
23-025-15	07/08/2015	2015 B1	Rear Door Glass Stain
23-026-15	06/17/2015	2015 DS	Water In Driver Foot Well - Park Release Cable Grommet Not Seated
23-027-15	06/20/2015	2014 VF	Rear Door Rattle Noise
23-028-15	06/20/2015	2016 FB	Matte Finish Care And Protection
23-029-15	07/21/2015	2015 KL	Water In Right Front Floor Footwell

## 2015 SERVICE BULLETIN/RECALL INDEX

**NUMBER      ISSUE DATE      MODELS      SUBJECT**

### **GROUP 24 - HEATING & AIR CONDITIONING**

24-001-15	02/27/2015	2014 WK	Slight Diesel Odor In The Vehicle
24-002-15	07/24/2015	2012-2013 WD	Flash: Rear HVAC Blower Controller Can Not Change Blower Speed
24-003-15	07/31/2015	2015 BU	Air Conditioning Inoperative

### **GROUP 25 - EMISSIONS CONTROL**

25-001-15	05/30/2015	2014-2015 D2 2014-2015 DD 2014-2015 DJ 2014-2015 DP	Diesel Exhaust Fluid (DEF) Level Gauge Inaccurate Or Stuck
-----------	------------	--	--

### **GROUP 28 - RECALLS**

RC-P27-15	03/27/2015	2011-2012 DD 2011-2012 DP	Customer Satisfaction Notification P27 - Engine Coolant Hose Bundle
RC-P29-15	04/22/2015	2013 DS	Customer Satisfaction Notification P29 - Reprogram Radio Frequency Hub Module
RC-P30-15	03/12/2015	2014 D2 2014 DD 2014 DJ	Customer Satisfaction Notification P30 - Engine Oil Filter Adapter
RC-P35-15	01/28/2015	2013 D2 2013 DJ	Emissions Recall P35 - Diesel Particulate Filter
RC-P66-15	01/15/2015	2015 MK	Emissions Recall P66 - VECI Label
RC-P72-15	03/13/2015	2015 JK	Emissions Recall P72 - Reprogram Powertrain Control Module
RC-P73-15	05/19/2015	2005-2010 WK 2006-2010 XK	Customer Satisfaction Notification P73 - Reprogram Final Drive Control Module

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
RC-P76-15	01/21/2015	2015 PF	Safety Recall P76 - Reconfigure Body Control Module
RC-P77-15	06/18/2015	2005 DR	Safety Recall P77 - Rear Axle Pinion Nut
RC-P78-15	05/13/2015	2005 DH 2003-2005 DR 2004-2005 HB 2005 LX 2005 ND	Safety Recall P78 - Passenger Airbag Inflator
RC-P80-15	04/15/2015	2006-2007 D1 2006-2007 DH 2006-2007 DR 2006-2007 ND	Safety Recall P80 - Clutch Interlock Switch
RC-P81-15	01/30/2015	2006-2007 D1 2007 DC 2005-2007 DH 2004-2007 DR 2004-2007 HB 2007 HG 2005-2007 LX 2005-2007 ND	Safety Recall P81 - Driver Airbag Inflator
RC-R01-15	04/16/2015	2014-2015 KL 2015 UF	Customer Satisfaction Notification R01 - Reprogram Transmission and Powertrain Control Modules
RC-R02-15	07/01/2015	2014-2015 VF	Emissions Recall R02 - VECI Label
RC-R03-15	07/18/2015	2009-2010 JC 2008-2010 RT	Safety Recall R03 - Wireless Ignition Node Module
RC-R04-15	06/04/2015	2014-2015 DS	Emissions Recall R04 - Exhaust High Frequency Decoupler
RC-R05-15	02/25/2015	2014-2015 KL	Safety Recall R05 - Reprogram Occupant Restraint Control Module
RC-R06-15	02/06/2015	2002-2003 KJ 2002-2004 WJ 2003-2004 ZB	Safety Recall R06 - Occupant Restraint Control Module

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
RC-R07-15	04/23/2015	2015 LA 2015 LD	Safety Recall R07 - Fuel Rail Crossover Hose
RC-R08-15	06/09/2015	2015 UF	Safety Recall R08 - Transaxle Park Rod
RC-R09-15	07/31/2015	2012-2013 WD 2011-2013 WK	Safety Recall R09 - Fuel Pump Relay
RC-R13-15	05/29/2015	2006 KJ 2006 TJ 2006 ZB	Safety Recall R13 - Clutch Interlock Switch
RC-R14-15	06/27/2015	2013-2014 ZD	Safety Recall R14 - Outside Door Handle Switch
RC-R15-15	05/21/2015	2013-2015 FF	Safety Recall R15 - Reprogram Electric Vehicle Control Module
RC-R16-15	05/08/2015	2009-2010 DM 2011-2012 DP	Safety Recall R16 - Steering Linkage
RC-R17-15	06/09/2015	2014-2015 DP	Safety Recall R17 - Reprogram Powertrain Control Module
RC-R19-15	04/30/2015	2015 VM	Safety Recall R19 - Side Air Bag Inflatable Curtains
RC-R20-15	06/09/2015	2013-2015 FF	Safety Recall R20 - Reprogram Electric Vehicle Control Unit
RC-R21-15	06/16/2015	2015 KL	Emissions Recall R21 - VECI Label
RC-R22-15	05/22/2015	2015 LA	Safety Recall R22 - Left Side Air Bag Inflatable Curtain Rear Bolt
RC-R25-15	06/12/2015	2006-2007 D1 2007 DC 2009 DC 2005-2007 DH 2004-2008 DR 2004-2008 HB 2007 HG 2005-2010 LX	Safety Recall R25 - Driver Airbag Inflator

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
		2005-2011 ND	
RC-R26-15	06/20/2015	2003 DR 2007-2008 VB	Safety Recall R26 - Passenger Airbag Inflator
RC-R30-15	07/10/2015	2001-2005 ST	Safety Recall R30 - Passenger Sun Visor
RC-R32-15	07/29/2015	2011-2015 JC	Safety Recall R32 - Engine Beauty Cover
RC-R33-15	07/01/2015	2015 WD 2015 WK	Safety Recall R33 - Rear Suspension Lower Control Arms
RC-R37-15	07/14/2015	2008-2010 LC	Safety Recall R37 - Driver Airbag Inflator
RC-R38-15	07/24/2015	2015 WD 2015 WK	Safety Recall R38 - Rear Suspension Lower Control Arms
RC-R40-15	07/30/2015	2013-2015 D2 2013-2015 DD 2013-2015 DJ 2013-2015 DP 2013-2015 DS 2014-2015 KL 2015 LA 2015 LD 2015 LX 2015 UF 2014-2015 WD 2014-2015 WK 2013-2015 ZD	Safety Recall R40 - Radio Security Vulnerability

### GROUP 29 - GLOBAL RECALLS

RC-IP10-15	02/26/2015	2014 KL	Safety Recall P10 - Wiring Harness Interference
RC-IP27-15	03/27/2015	2011-2012 DD 2011-2012 DP	Customer Satisfaction Notification P27 - Engine Coolant Hose Bundle
RC-IP29-15	04/22/2015	2013 DS	Customer Satisfaction Notification P29 - Reprogram Radio Frequency Hub Module

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
RC-IP30-15	03/12/2015	2014 D2 2014 DD 2014 DJ	Customer Satisfaction Notification P30 - Engine Oil Filter Adapter
RC-IP35-15	01/28/2015	2013 D2 2013 DJ	Emissions Recall P35 - Diesel Particulate Filter Wiring
RC-IP60-15	02/20/2015	2011-2014 LC 2011-2014 LD 2011-2014 LX 2011-2014 WD 2012-2014 WK	Safety Recall P60 - Alternator
RC-IP61-15	05/28/2015	2011-2013 JK	Safety Recall P61 - Heated Power Side View Mirror Wire Harness
RC-IP65-15	04/17/2015	2010-2014 D2 2010 DC 2011-2014 DD 2010-2014 DJ 2010 DM 2011-2014 DP	Safety Recall P65 - Diesel Fuel Heater Electrical Connector
RC-IP66-15	01/15/2015	2015 MK	Emissions Recall P66- VECI Label
RC-IP67-15	04/27/2015	2014 WD 2014 WK	Safety Recall P67 - Occupant Restraint Control Module
RC-IP72-15	03/13/2015	2015 JK	Emissions Recall P72 - Reprogram Powertrain Control Module
RC-IP73-15	05/19/2015	2009-2010 W2 2005-2010 WH 2006-2010 XH	Customer Satisfaction Notification R73 - Reprogram Final Drive Control Module
RC-IP77-15	06/09/2015	2005 DR	Safety Recall P77 - Rear Axle Pinion Nut
RC-IP80-15	04/15/2015	2006-2007 DR 2006-2007 ND	Safety Recall P80 - Clutch Interlock Switch

## **2015 SERVICE BULLETIN/RECALL INDEX**

<u><b>NUMBER</b></u>	<u><b>ISSUE DATE</b></u>	<u><b>MODELS</b></u>	<u><b>SUBJECT</b></u>
RC-IR01-15	04/16/2015	2014-2015 KL 2015 UF	Customer Satisfaction Notification R01 - Reprogram Transmission and Powertrain Control Modules
RC-IR02-15	07/01/2015	2014-2015 VF	Emissions Recall R02 - VECI Label
RC-IR03-15	07/27/2015	2009-2010 JC 2008-2010 RT	Safety Recall R03 - Wireless Ignition Node Module
RC-IR04-15	06/04/2015	2014-2015 DS	Emissions Recall R04 - Exhaust High Frequency Decoupler
RC-IR05-15	02/24/2015	2014-2015 KL	Safety Recall R05 - Reprogram Occupant Restraint Control Module
RC-IR07-15	04/23/2015	2015 LA 2015 LD	Safety Recall R07 - Fuel Rail Crossover Hose
RC-IR08-15	06/09/2015	2015 UF	Safety Recall R08 - Transaxle Park Rod
RC-IR10-15	03/04/2015	2015 BU	Safety Recall R10 - Rear Seat Center Seatbelt Buckle
RC-IR11-15	05/08/2015	2003 DR	Safety Recall R11 - Passenger Airbag Inflator
RC-IR12-15	05/29/2015	2015 BU	Customer Satisfaction Notification R12 - Software Updates
RC-IR14-15	06/26/2015	2013-2014 ZD	Safety Recall R14 - Outside Door Handle Switch
RC-IR15-15	05/19/2015	2013-2015 FF	Safety Recall R15 - Reprogram Electric Vehicle Control Unit
RC-IR16-15	05/07/2015	2009-2010 DM 2011-2012 DP	Safety Recall R16 - Steering Linkage
RC-IR17-15	06/09/2015	2014-2015 DP	Safety Recall R17 - Reprogram Powertrain Control Module
RC-IR19-15	04/30/2015	2015 VM	Safety Recall R19 - Side Air Bag Inflatable Curtains
RC-IR21-15	06/16/2015	2015 KL	Emissions Recall R21 - VECI Label
RC-IR22-15	05/22/2015	2015 LA	Safety Recall R22 - Left Side Air Bag Inflatable Curtain Rear

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
			Bolt
RC-IR25-15	07/18/2015	2006-2007 D1 2007 DC 2005-2007 DH 2009-2010 DM 2004-2008 DR 2004-2008 HB 2007 HG 2006-2007 L2 2006-2008 LE 2005-2010 LX 2005-2011 ND 2006-2007 NM	Safety Recall R25 - Driver Airbag Inflator
RC-IR26-15	06/20/2015	2003 DR 2007-2008 VB	Safety Recall R26 - Passenger Airbag Inflator
RC-IR33-15	06/30/2015	2015 WD 2015 WK	Safety Recall R33 - Rear Suspension Lower Control Arms
RC-IR37-15	07/14/2015	2008-2010 LC	Safety Recall R37 - Driver Airbag Inflator
RC-IR38-15	07/24/2015	2015 WD 2015 WK	Safety Recall R38 - Rear Suspension Lower Control Arms

### GROUP 30 - CANADIAN RECALLS

RC- CP35-15	03/18/2015	2013 D2 2013 DJ	EMISSIONS RECALL P35 – DIESEL PARTICULATE FILTER WIRING
RC-CP27-15	04/07/2015	2011-2012 DD 2011-2012 DP	CUSTOMER SATISFACTION NOTIFICATION P27 - ENGINE COOLANT HOSE BUNDLE
RC-CP29-15	04/27/2015	2013 DS	CUSTOMER SATISFACTION NOTIFICATION P29 - REPROGRAM RADIO FREQUENCY HUB MODULE
RC-CP30-15	03/16/2015	2014 D2 2014 DD 2014 DJ	CUSTOMER SATISFACTION NOTIFICATION P30 - ENGINE OIL FILTER ADAPTER

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
RC-CP66-15	01/20/2015	2015 MK	EMISSIONS RECALL P66 - VEHICLE EMISSION CONTROL INFORMATION LABEL
RC-CP72-15	03/23/2015	2015 JK	EMISSIONS RECALL P72 - REPROGRAM POWERTRAIN CONTROL MODULE
RC-CP73-15	05/29/2015	2005-2010 WK 2006-2010 XK	CUSTOMER SATISFACTION NOTIFICATION P73 - REPROGRAM FINAL DRIVE CONTROL MODULE
RC-CP76-15	02/05/2015	2015 PF	SAFETY RECALL P76 - RECONFIGURE BODY CONTROL MODULE
RC-CP77-15	07/02/2015	2005 DR	SAFETY RECALL P77 - REAR AXLE PINION NUT
RC-CP80-15	03/18/2015	2006-2007 D1 2006-2007 DH 2006-2007 DR 2006-2007 ND	SAFETY RECALL P80 - CLUTCH INTERLOCK SWITCH
RC-CR01-15	06/10/2015	2014-2015 KL 2015 UF	CUSTOMER SATISFACTION NOTIFICATION R01- REPROGRAM TRANSMISSION AND POWERTRAIN CONTROL MODULES
RC-CR02-15	07/08/2015	2014-2015 VF	EMISSIONS RECALL R02 - VEHICLE EMISSION CONTROL INFORMATION (VECI) LABEL
RC-CR03-15	06/02/2015	2009-2010 JC 2008-2010 RT	SAFETY RECALL R03 - WIRELESS IGNITION NODE MODULE
RC-CR04-15	06/09/2015	2014-2015 DS	EMISSIONS RECALL R04 - EXHAUST HIGH FREQUENCY DECOUPLER
RC-CR05-15	02/27/2015	2014-2015 KL	SAFETY RECALL R05 - REPROGRAM OCCUPANT RESTRAINT CONTROL MODULE
RC-CR06-15	02/12/2015	2002-2003 KJ 2002-2004 WJ 2003-2004 ZB	SAFETY RECALL R06 - OCCUPANT RESTRAINT CONTROL MODULE

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
RC-CR07-15	04/24/2015	2015 LA 2015 LD	SAFETY RECALL R07 - FUEL RAIL CROSSOVER HOSE
RC-CR08-15	06/10/2015	2015 UF	SAFETY RECALL R08 - TRANSAXLE PARK ROD
RC-CR09-15	04/16/2015	2012-2013 WD 2012-2013 WK	SAFETY RECALL R09 - FUEL PUMP RELAY
RC-CR13-15	06/05/2015	2006 KJ 2006 TJ 2006 ZB	SAFETY RECALL R13 - CLUTCH INTERLOCK SWITCH
RC-CR14-15	07/09/2015	2013-2014 ZD	SAFETY RECALL R14 - OUTSIDE DOOR HANDLE SWITCH
RC-CR16-15	05/07/2015	2011-2012 DJ 2009-2010 DM 2008 DR	SAFETY RECALL R16 - STEERING LINKAGE
RC-CR17-15	06/09/2015	2014-2015 DP	SAFETY RECALL R17 - REPROGRAM POWERTRAIN CONTROL MODULE
RC-CR19-15	05/07/2015	2015 VM	SAFETY RECALL R19 - SIDE AIR BAG INFLATABLE CURTAINS
RC-CR22-15	06/02/2015	2015 LA	SAFETY RECALL R22 - LEFT SIDE AIR BAG INFLATABLE CURTAIN REAR BOLT
RC-CR25-15	06/18/2015	2006-2007 D1 2009 D1 2007 DC 2009 DC 2005-2007 DH 2009 DH 2009-2010 DM 2004-2008 DR 2004-2008 HB 2007 HG 2005-2010 LX 2005-2011 ND	SAFETY RECALL R25 - DRIVER AIRBAG INFLATOR

## 2015 SERVICE BULLETIN/RECALL INDEX

<u>NUMBER</u>	<u>ISSUE DATE</u>	<u>MODELS</u>	<u>SUBJECT</u>
RC-CR30-15	07/10/2015	2001-2005 ST	SAFETY RECALL R30 - PASSENGER SUN VISOR
RC-CR33-15	07/02/2015	2015 WD 2015 WK	SAFETY RECALL R33 - REAR SUSPENSION LOWER CONTROL ARMS
RC-CR38-15	07/24/2015	2015 WD 2015 WK	SAFETY RECALL R38 - REAR SUSPENSION LOWER CONTROL ARMS